

YSHIELD® GCS | Grounding connection Screw

Grounding connection with two plates that get screwed together. For all electrically conductive fabrics, fleeces, meshes.



Grounding connection with two plates that get screwed together. For all electrically conductive fabrics, fleeces, meshes. **The two connecting plates must be screwed together - the material that is supposed to be grounded needs therefore to be perforated.**

- Connectivity: 1 cable connection
- Scope of delivery: 2 connecting plates 36x36x6 mm, all necessary screws, discs, cables lugs and a screwing tool with Torx®-Bits. Cable is not included in the scope of delivery - we recommend our pre-assembled grounding cables GL.